

RECEIVED

WATER WELL REPORT FOR AN EXISTING WELL

JUL 23 2013

DEPT OF ECOLOGY NWRO - WR

INSTRUCT	IONS:
----------	-------

Use this form if an original water well report was NEVER filed or is MISSING from Ecology records.

Your well must be properly tagged prior to submitting this form. Please fill in all blanks as completely as possible. If information is not know leave blank. After completing, mail the original form to: WA State Department of Ecology, PO Box 47600, Olympia, WA, 98504-

7600, ATTN: Marian Bruner.	A C A =7 =7 ?
CURRENT USE: ☐ Domestic ☐ Industrial ☐ Municipal	Unique Ecology Well ID Tag No.
□ DeWater □ Irrigation □ Test Well 🖼 Other Church	Water Right? If yes, attach copy ☐ Yes 12 No
DIMENSIONS: Diameter of well	Property Owner Name Camana Lutheran Church
Depth of completed well _96_ ft. if known.	Well Street Address 850 N. Heichel Ruad
CONSTRUCTION DETAILS Liner installed Yes No Unknown	Cir Camano Islandounty: Island
TYPE: □ PVC Steel □ Concrete Liner □ Other □ Unknown	Tax Parcel No. R 33221-078-0180
Perforations	LOCATION
SIZE of perfsin. byin. and no. of perfsft toft.	An accurate location of your well is very important. The Township, Range, Section and 1/4, 1/4 can be found on your legal description or through yor
Screens: Yes No Winknown Mf's name	county assessor's office
TYPE:	Sec_21_Twn.321/RS Circle
Diam. Slot Size from ft. to ft.	
Gravel/Filter Packed: Yes No Whown	D C B A
Materials paced fromft. toft.	This square represents one section of land,
Surface Seal: Yes No Dunknown If know, to what depth ft	E F G H which is approx. 640 acres. Within this
Materials used if	section, circle the letter
known:	M L K J that best represents the location of the well
PUMP: Dives Di No Mffr's Name	within this section.
Type: Goulds H.P. 74	N P Q R
WATER LEVELS: Land-surface elevation above mean sea	
levelft.	Lattitude/Longitude Note: Section, Township, Range still REQUIRED
Static Level ft. below top of casing Date measured	Lat Dec 43 Lat Min/Sect 14.52.00
Artesian pressure	Long Deg /22 Long Min/Sect 26.3286
	GPS Survey
WELL TESTS: Drawdown is amount water level is lowered below static level.	☐ Topographic Map ☐ Computer Generated
Was a pump test made? ☐ Yes ☐ No If yes, attach copy	Additional Information, if available:
☐ Unknown	☐ Location marked on topographic map (please attach)
Yield: 12 al./min. withft. drawdown afterhrs.	☐ Location marked on air photo (please attach)
	_
CERTIFICATION: The information reported above is	s true to the best of my knowledge and belief.
□ Driller ☐ Engineer □ Property Owner □ Other	Drilling Company Island County Health De
Driller D Engineer D Property Owner D Cares	Drilling Company Island Lounty Hally
Name Vin Sherman	Diraily Colliberty

Address of person completing this form: Signature <u></u> PO BOY 5000 Driller License No. City, State, Zip Couperile Date Signed 18

Dead end Road Vicinity Map of CAMAWO LUTHERAN CHURCH 850 N Heichel Rd 10 4Rav Protection Juscepti Dility H ssesment Circle of the church's well mater supply church North Property Line. Residences 5 year Protection Civele Playround Surround 1 Drilled an Well Scale 1"=100' Church Residence Church Somplex State HW4 532 > Stanwood 3 miles